

Message

From: Fennessy, Christopher [christopher.fennessy@Rocket.com]
Sent: 8/3/2018 6:58:18 PM
To: MacNicholl, Peter@DTSC (Peter.MacNicholl@dtsc.ca.gov) (Peter.MacNicholl@dtsc.ca.gov)
[Peter.MacNicholl@dtsc.ca.gov]; MacDonald, Alex@Waterboards (Alex.MacDonald@waterboards.ca.gov)
[Alex.MacDonald@waterboards.ca.gov]; Keller, Lynn [Keller.Lynn@epa.gov]
Subject: FW: [EXTERNAL] FW: investigation area
Attachments: ATT00001.txt; 154153_107_Figure_2_source_areas_RAP.pdf

Attached is a revised figure 2 for the RAP and the shape files to provide to the CAG so they can see the acreages of each area.

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Engineering Manager, Site Remediation
11260 Pyrites Way, Suite 125
Rancho Cordova, CA 95670
Ph: 916-355-3341
Fax: 916-355-6145
Email: Christopher.Fennessy@Rocket.com

From: Scott Forbess [mailto:SForbess@Geosyntec.com]
Sent: Friday, August 03, 2018 10:15 AM
To: Fennessy, Christopher
Subject: FW: [EXTERNAL] FW: investigation area

Please see attached.

Scott Forbess, P.E. (CA)
Senior Principal Engineer

Direct: 916.637.8329
Mobile: 530.400.5092

From: Grant Hurst
Sent: Friday, August 3, 2018 9:56 AM
To: Scott Forbess <SForbess@Geosyntec.com>
Subject: RE: [EXTERNAL] FW: investigation area

Here's this.

From: Scott Forbess
Sent: Friday, August 3, 2018 9:30 AM
To: Grant Hurst <GHurst@Geosyntec.com>
Subject: FW: [EXTERNAL] FW: investigation area

Scott Forbess, P.E. (CA)
Senior Principal Engineer

Direct: 916.637.8329
Mobile: 530.400.5092

From: Fennessy, Christopher <christopher.fennessy@Rocket.com>
Sent: Friday, August 3, 2018 9:11 AM
To: Scott Forbess <SForbess@Geosyntec.com>
Subject: RE: [EXTERNAL] FW: investigation area

Please add Open Space area acreage and Park area acreage. Make sure callouts point to area referred. Currently Area 40 callout does not reach the Area 40 rectangle.

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Engineering Manager, Site Remediation
11260 Pyrites Way, Suite 125
Rancho Cordova, CA 95670
Ph: 916-355-3341
Fax: 916-355-6145
Email: Christopher.Fennessy@Rocket.com

From: Scott Forbess [<mailto:SForbess@Geosyntec.com>]
Sent: Friday, August 03, 2018 8:46 AM
To: Fennessy, Christopher
Subject: FW: [EXTERNAL] FW: investigation area

Scott Forbess, P.E. (CA)
Senior Principal Engineer

Direct: 916.637.8329
Mobile: 530.400.5092

From: Grant Hurst
Sent: Friday, August 3, 2018 8:42 AM
To: Scott Forbess <SForbess@Geosyntec.com>
Subject: RE: [EXTERNAL] FW: investigation area

Shapefile attached as "area40_boundaries.zip". Figure 2 PDF also attached. Let me know if the callouts are okay, or if you'd like something different.

From: Fennessy, Christopher <christopher.fennessy@Rocket.com>
Sent: Friday, August 3, 2018 8:21 AM
To: Scott Forbess <SForbess@Geosyntec.com>
Cc: Grant Hurst <GHurst@Geosyntec.com>
Subject: RE: [EXTERNAL] FW: investigation area

My recommendation would be to use your figure and just identify the acreages. I had to put in a poly line for the shape on-top of the cad file, so may not be as accurate as your geometry.

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Engineering Manager, Site Remediation
11260 Pyrites Way, Suite 125
Rancho Cordova, CA 95670
Ph: 916-355-3341
Fax: 916-355-6145
Email: Christopher.Fennessy@Rocket.com

From: Scott Forbess [<mailto:SForbess@Geosyntec.com>]
Sent: Friday, August 03, 2018 8:20 AM
To: Fennessy, Christopher
Cc: Grant Hurst
Subject: RE: [EXTERNAL] FW: investigation area

Thanks. We will create the shape file for the CAG to include the investigation boundary from Figure 2 and the Area 40 property boundary from the CAD file. On Figure 2 we call out the acreage of both areas.

Scott Forbess, P.E. (CA)
Senior Principal Engineer

Direct: 916.637.8329
Mobile: 530.400.5092

From: Fennessy, Christopher <christopher.fennessy@Rocket.com>
Sent: Friday, August 3, 2018 8:17 AM
To: Scott Forbess <SForbess@Geosyntec.com>
Subject: RE: [EXTERNAL] FW: investigation area

Original figure is correct (red line for investigation area). I was eyeballing when I created mine.

Christopher M. Fennessy, P.E.
Aerojet Rocketdyne, Inc.
Engineering Manager, Site Remediation
11260 Pyrites Way, Suite 125
Rancho Cordova, CA 95670
Ph: 916-355-3341

Fax: 916-355-6145

Email: Christopher.Fennessy@Rocket.com

From: Scott Forbess [<mailto:SForbess@Geosyntec.com>]

Sent: Friday, August 03, 2018 8:15 AM

To: Fennessy, Christopher

Subject: [EXTERNAL] FW: investigation area

The screen shots below are from the CAD figure you provided and Figure 2 from the RAP, respectively. Notice the Investigation area between the two differs in the southwest corner. Is the CAD figure you provided correct?

Scott Forbess, P.E. (CA)

Senior Principal Engineer

Direct: 916.637.8329

Mobile: 530.400.5092


From: Grant Hurst

Sent: Friday, August 3, 2018 8:12 AM

To: Scott Forbess <SForbess@Geosyntec.com>

Subject: investigation area





Grant Hurst, P.G. (CA)
Project Hydrologist

3043 Gold Canal Drive
Suite 100
Rancho Cordova, CA 95670
Direct: 916.637.8333

Geosyntec[®]
consultants

engineers | scientists | innovators

Mobile: 661.549.7627
www.Geosyntec.com

This electronic mail message contains information that (a) is or may be LEGALLY PRIVILEGED, CONFIDENTIAL, PROPRIETARY IN NATURE, OR OTHERWISE PROTECTED BY LAW FROM DISCLOSURE, and (b) is intended only for the use of the Addressee(s) named herein. If you are not the intended recipient, an addressee, or the person responsible for delivering this to an addressee, you are hereby notified that reading, using, copying, or distributing any part of this message is strictly prohibited. If you have received this electronic mail message in error, please contact us immediately and take the steps necessary to delete the message completely from your computer system.